

**PROFORMA FOR SAFE DRINKING WATER AND  
SANITARY CONDITION CERTIFICATE**

No. : **08**

Dated: **16.02.2026**

It is certified that an inspection team headed by **JOY KUMAR MINZ, ASSISTANT ENGINEER, DW & S DIVISION, LOHARDAGA** (Name of Officers with designation) from **DW & S DIVISION, LOHARDAGA** inspected the **KGBV CM SCHOOL OF EXCELLENCE, LOHARDAGA, Vill:Kujra, PO:Kujra, PS:Lohardaga, Dist: Lohardaga (Jharkhand)** (Name & Address of the school) on **16.02.2026** (date of inspection) and on the basis of Water Test Report (Attached) Certified that the **KGBV CM SCHOOL OF EXCELLENCE, LOHARDAGA** (Name of school) has safe drinking water facilities for the student sand members of staff of the institution. School also maintains the hygienic sanitation condition in the school building & the campus as per norms pre scribed by the Central/State/U.T.Govt.

This certificate is valid till **Next Inspection.**

Signature with Seal:.....  
Name : **JOY KUMAR MINZ**  
Designation : **ASSISTANT ENGINEER,**  
Office/Dept : **DW & S DIVISION, LOHARDAGA**

*JY Minz*  
16.02.26

सहायक अभियंता  
पयजल एवं स्व० अ० प्रमडल

मिटर ५०११

To,  
**WARDEN,**  
**KGBV CM SCHOOL OF EXCELLENCE, LOHARDAGA**  
**Vill:Kujra, PO: Kujra, Dist: Lohardaga.**  
**PIN – 835302 (JHARKHAND)**

Note:The certificate is to be issued by authorized officer/PHEDLab/local bodies